

Blancco Drive Eraser version 6.13.1 has been released!

Drive Eraser version 6.13.1 - Release notes

Bug fixes:

- **ALBUS-6928** - The Slovak language could not be preconfigured in HW images.
- **ALBUS-7124** - Custom digital signatures did not work.
- **ALBUS-6772** - Samsung PM1723b / PM1723a NVMe was not detected.
- **ALBUS-7105** - Samsung PM1633a SAS SSD was not detected.
- **ALBUS-6894** - The Erasure Resume functionality did not work.
- **ALBUS-7016** - SK hynix SC308 SATA SSD could not be erased.
- **ALBUS-7104** - SSD on Dell Latitude 7300 was not detected.
- **ALBUS-7056** - The WLAN adapter MAC-address changed between restarts.
- **ALBUS-7146** - Spinning down SAS/SCSI drives did not work, the "standby" label was also not shown.
- **ALBUS-7107** - Filling in the BMC credentials via a popup window did not work.
- **ALBUS-6482** - The message indicating that the Self-test result was completed was truncated.