Blancco Drive Eraser version 6.16.0 and Drive Eraser Configuration Tool 2.16.0 have been released!

Drive Eraser 6.16.0 and Configuration Tool 2.16.0 - Release notes

Features:

- **ALBUS-7276** - Intelligent Business Routing - Workflows with Custom Fields and Questions.
- **ALBUS-6461** - Erasure of Remapped Sectors as Optional or Mandatory.
- **ALBUS-7003** - Reporting "Blancco SSD Erasure" Compliance with NIST.
- **ALBUS-6803** - Detection of NVMe Compliance with TCG Specifications.
- **ALBUS-7272** - Improved Detection of SMART ATA Attributes, pt 2.
- **ALBUS-6410, ALBUST-681** - Validation of TLS Certificates from BMC.

Bug fixes:

- **ALBUS-7309, ALBUS-7297** - The Condition action has been improved and supports additional variables and functions.
- **ALBUS-7357** - The popup indicating the presence of SSD, NVMe, eMMC or SSHD drives has been removed.
- **ALBUS-7472** - Removing legacy messages from the report related to SSD/NVMe/eMMC erasure.
- **ALBUS-7347** - Static fallback settings are disabled in Workflow mode.
- **ALBUS-7367** - Reusing the same Entity Info within a Workflow duplicated it.
- **ALBUS-7327** - The parameter libata.allow_tpm=1 was sometimes not detected.
- **ALBUS-7212** - Some Sandforce SSD's reported a wrong drive size and serial number.
- **ALBUS-7431** - External drives "Seagate Expansion Desktop" 8 TB failed the erasure after formatting.
- **ALBUS-7493** - The popup to switch from RAID to HBA blocked the automatic erasure.
- **ALBUS-7346** - Workflow diagnostics are not executed on machines lacking the tested component.
- **ALBUS-5340** - Fixing a flaw in the erasure of remapped sectors.
- **ALBUS-7189, ALBUS-6009, ALBUS-7187, ALBUS-7559, ALBUS-7182** - Various fixes related to SMART attributes detection and reporting.
- **ALBUS-7533** - The Intel Core i7-8850H processor was reporting a low max speed.
- **ALBUS-6838, ALBUS-6855** - Fix for an incorrect battery capacity detection.
- **ALBUS-7561** - The XML report is updated before testing a Workflow Condition-action.
- **ALBUST-683** - Disabling the RPD mode disables per-drive custom fields.
- **ALBUST-670** - Static fallback setting "Purge to Clear" is disabled in Workflow mode.