

E800 safety features

- The E800 Molex adapters come with safety features, including a fuse kit for each drive and a thermal kill switch for appliances with Fibre channel bays.
- To check and replace a blown fuse, twist the black housing connecting the 5V (Red) and 12V (Yellow) power cables and check for signs of damage. Should a fuse be damaged, simply remove it and replace it with a new fuse (much like a AAA Battery).
- A Thermal fuse is installed to disrupt power to the bay of any Fibre Channel drive which generates an unsafe amount of heat. This will automatically reset once the internal temperature of the appliance returns to normal operating levels.