Drive Eraser Configuration Tool version 2.3 has been released!

Configuration Tool 2.3 - Release notes:

Features:

- ALBUST-425 Ability to configure Fingerprint in a sector < 200.
- ALBUST-426 Ability to configure "flr=disabled" as a customized booting option.

Fixes:

- ALBUST-421 Fix for an issue where Image Configuration Tool drops FLR kernel command.
- ALBUST-422 Fix for an issue where mandatory value prevents saving and sending erasure report although all fields have values.
- ALBUST-423 Fixed Help-button which was pointing to old user manual.
- ALBUST-424 Fix for an issue where changing the default booting option does not display it in the splash screen.