

Blancco 5Drive EraserHBA

SAS/SATA HBA					0		HBA
Dell MegaRAID Perc6/e	5.5.0		5.6.1	Dell PowerEdge 2970	Dell PowerVault MD 1000	2 x Seagate Barracuda 80 GB SATA HDD 1SATA-to-SAS1SATA-to-SAS	Package 6.3.1-0003 FW version 1.22.32-1371 Bios version 2.04.00 CtrlR version 1.02-015B
	5.6.0		5.6.1	Dell PowerEdge 2970	Dell PowerVault MD 1000	2 x Seagate Barracuda 80 GB SATA HDD 1SATA-to-SAS1SATA-to-SAS	Package 6.3.1-0003 FW version 1.22.32-1371 Bios version 2.04.00 CtrlR version 1.02-015B
	5.7.2			Dell PowerEdge 2970	Dell PowerVault MD 1000	2 x Seagate Barracuda 80 GB SATA HDD (: 512) 1SATA-to-SAS1SATA-to-SAS 2 x Hitachi 73 GB SAS HDD (HUS153073VLS300, : 520)	Package 6.3.1-0003 FW version 1.22.32-1371 Bios version 2.04.00 CtrlR version 1.02-015B
Dell MegaRAID Perc5/i	5.7.2			Dell PowerEdge 2970	()	2 x Seagate 36GB SAS HDD (ST936751SS, : 512)	Package 5.2.1-0067 FW version 1.03.40-0316 Bios version MT28-8 CtrlR version 1.04-019A
HP SmartArray 420i HP SmartArray 420	5.6.0			HP ProLiant DL360p Gen8		SAS/HDDs: HP EG0450FBVFM (450 GB) SAS/SSDs: HP EO0200FBRVV (200 GB) SATA/HDDs: (HP) MM0500GBKAK (500 GB) (HPSATA)	FW version 5.42 Option ROM Configuration for Arrays, version 8.50.65.00
HP SmartArray 420	5.7.0.1	(HBAFW)				SAS/HDDs: HP DH072BAAKN (73.4GB) SATA/HDDs: Western Digital WD3200BEKT-7 (320GB) SATA/SSD : Kingston SH103S3 (240GB)	FW version 5.42
	5.7.2					SAS/HDDs: HP EH0072FARUA (73 GB) SATA/HDDs: Western Digital WD3200BEKT-7 (320GB)	FW version 5.42
HP SmartArray P800	5.6.0	SATASAS		HP ProLiant DL380 Gen5	MSA70 SAS(/SATA)	SAS/HDDs: 10 x HP DH072BAAKN & 8 x HP EH0072FARUA (73 GB) SATA/HDDs: 5 x Western Digital WD3200BEKT-75PVM1, 1 x Samsung HM321HI & 1 x Toshiba MK3261GSYN (320 GB)	FW version 7.22 Option ROM Configuration for Arrays, version 8.20.15.00
	5.7.2	Aperiodic random overwrite	Aperiodic random overwrite5.7.0.1	HP ProLiant DL380 Gen5	MSA70 SAS(/SATA)	SAS/HDDs: HP DH072BAAKN & HP EH0072FARUA (73 GB) SATA/HDDs: Western Digital WD3200BEKT-75PVM1 (320 GB)	FW version 7.22 Option ROM Configuration for Arrays, version 8.20.15.00
LSI SAS 9211-8i	5.8.0	SAS/HDD SATA/HDD		8 bay Drive Eraser appliance		SATA/HDDs: 2 x Western Digital WD2503ABYZ-011FA0 (250GB) SAS/HDDs: 2 x Seagate ST1000NM0023 (1000GB)	MPT FW Revision: 15.00.00.00-IT MPT2BIOS: 7.29.00.00 (2012.11.12) NVDATA Version: 0F.00.00.05
FC HBA					0		HBA
LSI Logic 7204EP-LC	5.8.0			8 bay Drive Eraser appliance		2 x Seagate SX373405FC (73GB)	Fusion MPT-v1.05.00 FC MPTBIOS-2.02.06
SCSI HBA					0		HBA
IBM ServeRAID-7k	5.8.0			IBM eserver xSeries 346	()	2 x IBM-ESXS, MAW3073NC FN (73 GB)	Bios/FW 7.10.20
Adaptec 29320LPE	5.8.0			8 bay Drive Eraser appliance		1 x Compaq BD07285A25 (73GB) 1 x Compaq BD14689BB9 (146GB)	Utility v4.31.9
Dell MegaRAID Perc2 [MEGARAIID_LEGACY card]	5.6.0			Dell PowerEdge 4400	() SCSI	18.2GB SCSI	FW version 1.06 BIOS version 1p00
	5.7.0	Blancco 5.7.0		Dell PowerEdge 4400	() SCSI	18.2GB SCSI	FW version 1.06 BIOS version 1p00