

# Note on 3PAR 10xxx Series

If you are currently attempting to erase a 3PAR 10xxx series with Blanco Enterprise Array 2U, please note:

- There is a known issue with the 3Par 10xxx series where drive detection is incomplete.
- The current work-around is to connect directly at the shelf level utilizing the fibre channel port on the front of the appliance

Please note the shelves will not support daisy-chaining