

# 24 Bay Drive Eraser

Blancco 24 Bay Drive Eraser is an industrial solution designed for fast, high-volume erasure of up to 24 drives per session of loose SAS/SATA/SSD hard drives. The 24 Bay Drive Eraser is a turn-key setup complete with data erasure software and hardware and customizable reporting capabilities.

- **Product name:** Blancco 24 Bay Drive Eraser
- **Old product name:** Enterprise Erase E2400
- **Official Blancco web site link:** <https://www.blancco.com/products/data-erasure-hardware/#24bay>
- **Access to Product Manuals require customers to log into our [Support Portal](#)**

## Knowledge Base articles:

- [After updating a Blancco Hardware Appliance only GRUB is displayed](#)
- [BlanccoCMOS](#)
- [BlanccoGRUB](#)
- [Clearing CMOS on Blancco Hardware Appliances](#)
- [CMOS auf Blancco Hardware-Geräten löschen](#)
- [Controller \(HBA\) and Hard Drives Check Procedure via HBA BIOS](#)
- [Controller Card \(HBA\) Check Procedure](#)
- [E800 safety features](#)
- [Erasure progress reset for drives connected to E800/E2400](#)
- [Front USB Ports are not detected](#)
- [Hard Drives Check Procedure](#)
- [Nach der Aktualisierung einer Blancco Hardware-Appliance wird lediglich GRUB angezeigt](#)
- [No drive\(s\) detected in the E800 drive bays \(no drives showing in the Blancco 5 GUI\)](#)
- [No power to the E800 bays \(Green LED is not lit\)](#)
- [The hardware unit does not power on](#)
- [Unit has no video](#)
- [What is included in the shipment of Enterprise Erase E2400](#)



Blancco US LLC  
Austin, TX 78759

**Model:** E2400  
**Volts:** 100-240 Vac  
**Amp:** 12-6 A  
**Freq:** 50/60Hz



**Assembled in USA  
with Foreign and  
Domestic Parts**

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.