

Drive Eraser Configuration Tool version 2.2.1 has been released!

Configuration Tool 2.2.1 - Release notes

Bug fixes:

- **ALBUST-421** - Fix for an issue where Configuration Tool drops FLR kernel command from booting parameters.
- **ALBUST-423** - Fix for an issue where Help-button points to old user manual.