

# Blancco Mobile Diagnostics and Erasure 4.0.2 is now released!

Mobile Diagnostics and Erasure 4.0.2 - Release notes

Due to the increasingly larger sizes of iOS firmware installation packages, the minimum RAM needed on a machine running BMDE should be increased from 4GB (old minimum) to 8GB. iOS firmware design requires that large portions of the image be uncompressed in memory which is driving the need for increasing RAM.

- **PHEN-4250** - iPhone 11 Support Added.
- **PHEN-4265, BTS-29581** - USB "No Resources" Issue.
  - This has been fixed.
- **PHEN-4302** - FMiP Source in Report is Incorrect When Running Advanced FMiP Check.
  - This has been fixed.